

Source Identification of a Continuous Dry Weather Stormwater Collection System Discharge

Jennifer D. Cearfoss
U.S. Army CHPPM

Environment, Energy & Sustainability
Symposium and Exhibition
7 May 2009

Report Documentation Page			<i>Form Approved OMB No. 0704-0188</i>	
<p>Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.</p>				
1. REPORT DATE 07 MAY 2009	2. REPORT TYPE	3. DATES COVERED 00-00-2009 to 00-00-2009		
4. TITLE AND SUBTITLE Source Identification of a Continuous Dry Weather Stormwater Collection System Discharge			5a. CONTRACT NUMBER	
			5b. GRANT NUMBER	
			5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)			5d. PROJECT NUMBER	
			5e. TASK NUMBER	
			5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Center for Health Promotion and Preventive Medicine (CHPPM),Aberdeen Proving Ground,MD,21010			8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)			10. SPONSOR/MONITOR'S ACRONYM(S)	
			11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited				
13. SUPPLEMENTARY NOTES Presented at the NDIA Environment, Energy Security & Sustainability (E2S2) Symposium & Exhibition held 4-7 May 2009 in Denver, CO.				
14. ABSTRACT				
15. SUBJECT TERMS				
16. SECURITY CLASSIFICATION OF: a. REPORT unclassified			17. LIMITATION OF ABSTRACT Same as Report (SAR)	18. NUMBER OF PAGES 31
b. ABSTRACT unclassified			c. THIS PAGE unclassified	19a. NAME OF RESPONSIBLE PERSON

Background

- ▶ Malmstrom Air Force Base (MAFB) is located in Great Falls, MT
- ▶ Significant amount of dry weather flow present in the storm sewer collection system
- ▶ Continuous flow discharges to Whitmore Ravine eventually reaching the Missouri River

Issues

- ▶ The constant high flow of water has caused considerable erosion in Whitmore Ravine
- ▶ The erosion has led to:
 - Increased deposition in the Missouri River
 - Public protest over damage to private farm land and the adjoining state managed easement
 - Congressional concern over the DoD impact to the watershed






Project Goals

- ▶ Determine the source(s) of the continuous dry weather flow
- ▶ Quantify the flow
- ▶ Evaluate alternatives for managing the flow


Stormwater Collection System

- ▶ Majority of the system built in the 1950's
- ▶ Traditional concrete piping throughout the main part of the installation
- ▶ Flight line constructed using a combination of concrete piping and drain tile
- ▶ Nine drainage areas on the installation



Approach

- ▶ In-situ flow analysis at key sections of the MAFB collection system during dry weather
- ▶ Monitoring points (MPs) were set up at the three outfalls experiencing dry weather flow
- ▶ The dry weather flow at each outfall was followed upstream and additional MPs were established



Whitmore Ravine


- ▶ MPs were also established in Whitmore Ravine
- ▶ To determine if any additional flow was contributing to the final discharge at the Missouri River
- ▶ Continuous monitoring of these discharges was not possible
- ▶ Instantaneous flow monitoring was performed daily

Analytical Sampling

- ▶ Used to compare dry weather flow with potential water sources to determine origin
- ▶ Grab samples from potable water and ground water were used for comparison
- ▶ Conductivity, pH and cation/anion analysis were performed

Results – Outfall 1

- ▶ Encompasses all housing areas, western portion of base operations and southwestern tip of flight line
- ▶ Discharge ~ 44 gpm
- ▶ 51% of total dry weather flow




Groundwater Infiltration




Results – Outfall 2


- ▶ Encompasses the central portion of base operations
- ▶ Discharge ~ 6 gpm
- ▶ 7% of total dry weather flow



Results – Outfall 3

- ▶ Encompasses the northeast portion of base operations and almost the entire flight line
- ▶ Discharge ~ 36 gpm
- ▶ 42% of the total dry weather flow





Results – Whitmore Ravine

Date	Flow Rates (gpm)					
	East Fork (MP 8)	Outfall 3	% From MAFB	West and Middle Forks (MP 9)	Outfalls 1 + 2	% From MAFB
16 Apr 08	43.0	27.1	63%	19.9	13.9	70%
17 Apr 08	35.5	27.6	78%	23.3	15.6	67%
15 May 08	57.4	33.9	59%	63.4	54.9	87%
16 May 08	35.5	27.1	76%	35.8	47.9	100%
17 May 08	19.7	25.2	100%	34.8	47.2	100%
18 May 08	26.1	27.6	100%	50.2	39.8	79%
19 May 08	19.7	23.3	100%	41.1	23.9	58%
Average	33.8	27.4	81%	38.4	34.7	90%

Analytical Results

	Bicarbonate Alkalinity (mg/L as CaCO ₃)	Total Alkalinity (mg/L as CaCO ₃)	Sulfate (mg/L)	Chloride (mg/L)	Calcium (mg/L)	Magnesium (mg/L)	Potassium (mg/L)	Sodium (mg/L)
Dry Weather Flow	300	300	407	60.9	140	79	9.3	66
Potable Water	120	120	57.3	13.8	39	11	3	16
Ground Water	360	360	1460	53.5	390	260	36	290

	pH	Conductivity (mS/cm)	TDS (mg/L)
Dry Weather Flow	6.70	1.34	1000
Potable Water	6.60	0.35	220
Ground Water	6.55	3.71	2620

Summary

- ▶ Groundwater infiltration seems to be the main cause of the dry weather flow
- ▶ Two points of entry:
 - Joints of manholes collars and around piping
 - Drain tiles around the flight line

Alternatives Evaluation

- ▶ Reuse of dry weather flow for non potable water users
 - On-site irrigation
 - Vehicle washing
 - Non-contact cooling water
- ▶ Repair/Replacement of Stormwater Collection System
 - Disconnection/Replacement of stormwater lines
 - Lining the stormwater collection system

Alternatives Evaluation Cont'd

► On-site irrigation

- Water purchased from City of Great Falls (\$1,630 per MGD)

Month	Total Water Consumption (MGD)	Volume used for Irrigation (MGD)	Cost of Irrigation (\$)
October	15.0	3.0	4,890
November	11.2	0	0
December	13.6	0	0
January	13.1	0	0
February	11.6	0	0
March	10.4	0	0
April	11.8	0	0
May	17.7	5.7	9,291
June	21.1	9.1	14,833
July	43.2	31.2	50,856
August	59.1	47.1	76,773
September	34.5	22.5	36,675
Total	262.3	118.6	193,318

Alternatives Evaluation Cont'd

- ▶ Reuse for vehicle washing
 - Water management pond would be necessary
 - Construction of a wash rack near the pond
 - Piping to car washes
- ▶ Reuse for non-contact cooling water
 - Central Heat Plant at MAFB is designed to fire natural gas and/or coal
 - Operates October through May
 - When in operation uses ~70 gpm (100 KGal/day)

Alternatives Evaluation Cont'd

- ▶ Disconnection/Replacement of stormwater lines on the flight line
 - Could significantly decrease dry weather flow to outfalls 1 and 3
 - Would not remove all dry weather flow from collection system
- ▶ Lining stormwater collection system
 - Should reduce groundwater infiltration
 - Expensive

Conclusions/Recommendations


- ▶ No obvious solution for eliminating flow to Whitmore Ravine
- ▶ Reuse, repair and replacement alternatives will all require significant infrastructure changes and/or additions = expensive
- ▶ Best option for elimination dry weather flow:
Non potable water reuse
 - On-site irrigation in summer
 - Non-contact cooling water in the winter

Questions?



Jennifer D. Cearfoss
U.S. Army CHPPM
jennifer.cearfoss@us.army.mil
(410) 436-8160

Data Example



4/16/2008	34% of the day Total Flow (gal) Average Flow (gpm) Minimum Flow (gpm) Maximum Flow (gpm)	2690.04 5.46 1.73 12.70
4/17/2008	100% of the day Total Flow (gal) Average Flow (gpm) Minimum Flow (gpm) Maximum Flow (gpm)	7096.80 4.93 2.13 10.83
4/18/2008	100% of the day Total Flow (gal) Average Flow (gpm) Minimum Flow (gpm) Maximum Flow (gpm)	6730.20 4.67 1.37 13.09
4/19/2008	50% of the day Total Flow (gal) Average Flow (gpm) Minimum Flow (gpm) Maximum Flow (gpm)	2838.42 3.63 1.64 7.75

Hydrogeology

- ▶ MAFB sits atop a “bowl” filled with glacial till consisting of clay, sand and silt with gravel
- ▶ Overlying the till is a layer of glacial lake deposit composed of loose, easily erodible sand silt interspersed with clay
 - Can extend from surface to 50 ft deep
 - Contains a underlying layer of clay that may inhibit water from soaking further into the ground
- ▶ Water sits in this “bowl” and can be found very close to the surface